

Fault Log – June 2010

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
1. 1 slab badly broken and rising up	Mailmans Arms/Stag Hotel area	Mr Abbott	HCC (Highways)	Outstanding (Apr 10)
2. Road surface/potholes	Before & adjacent to Crown Hotel	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
3. Kerbs displaced in layby	Middle of Park Close, Clayhill	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
4. Kerbs displaced in layby	Adj to post box near Crown Stirrup, Clayhill	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
5. Loose stones between highway & running strip. Some loose stones now breaking due to continual hammering	Throughout High Street	Mr Abbott	HCC (Highways)	Ongoing – long term solution might be to replace with tarmac (Dec 09)
6. 20+ kerbs lose or displaced	Layby adj phone at Foxlease	Mr Abbott	HCC	Order with contractor (Dec 09)
7. Red blocks lose/protruding	Between Royals and Workmens Club	Mr Abbott	HCC informed	Ongoing (Dec 09)
8. Slab broken	Path from museum to coach park near path alongside museum	Mr Abbott	NFDC	Another loose slab has been done (Dec 09)
9. Kerb misplaced	North side of entrance to Beechen Lane	Mr Abbott	HCC	Ongoing (Dec 09)
10. Plastic post broken	Opposite Waterloo Arms	Mr Abbott	HCC	Part superseded by footpath work, 1 missing, 1 broken (Apr 10)
11. Kerbs misplaced	Queens Cottage corner opposite Queens House	Mr Abbott	HCC	Ongoing (Dec 09)
12. Look Left not repainted on pavement	Entrance to car park, Gosport Lane	Mr Abbott	HCC (Electrical Contractors)	Ongoing (Dec 09)
13. Kerb protruding – tripping hazard	Entrance Car Park, Gosport Ln, NS	Mr Abbott	HCC	Ongoing (Dec 09)
14. Safety post	Corner Gosport Lane	Mr Abbott	HCC	To be replaced (Dec 09)
15. Bad potholes	Bank to Gritnam	Mr Abbott	FC	Assessed Dec 09
18. Potholes and rough surface	Bank side of grid from A35	Mr Abbott	HCC (Highways)	Reported Dec 09
19. Posts missing struck by vehicle	Island at Goose Green/Shrubbs Hill	Mr Abbott	HCC (Highways)	Reported Dec 09
20. Bottom board on westbound road sign moved	Opposite Natural England	Mr Abbott	HCC	Reported Dec 09
22. Hydrant cover banging badly	Romsey Rd corner outside Antiques	Mr Abbott	HCC (Highways)	Reported Dec 09
25. Broken paving slabs	Outside Infant School	Mr Rollé	HCC (Highways)	Reported Mar 10
27. Raised manhole cover	Shrubbs Hill Road, after entrance to Shrubbs Hill Gardens	Mr Rollé	HCC (Highways)	Reported April 10
28. Cracked slabs	Outside Lyndhurst Infant School	Mr Rollé	HCC (Highways)	Reported April 10
29. Deep potholes in road	LHS corner of Garden Close	Mr Rollé	HCC (Highways)	Reported April 10
30. Bottom rail adrift on squeeze gate	Adj Lyndhurst Park Hotel	Mr Abbott	Forestry Commission	Reported April 10
31. Potholes in pavement	Outside 32 Queens Road	Mr Cornell	HCC	Reported May 10
32. General road pavement surface	Queens Road	Mr Cornell	HCC	Reported May 10
33. Overgrown hedging	Outside 20 Queens Road	Mr Cornell	HCC	Reported May 10
34. Potholes in pavement	Outside Ormonde House Hotel	Mr Cornell	HCC	Reported May 10

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
35. Overgrown hedging	Outside 9 Queens Road	Mr Cornell	HCC	Reported May 10
36. Raised BT cover/sunken surround	Opposite 3 Queens Road	Mr Cornell	HCC	Reported May 10
37. Potholes in pavement	Outside 7 Queens Road	Mr Cornell	HCC	Reported May 10
38. Raised manhole cover	Outside Meridien Garage	Mr Herbert	HCC	Reported June 10
39. Road sign partly displaced	Adj Queens Cottage	Mr Abbott	HCC	Reported June 10
40. Road sign partly displaced	Adj Church steps	Mr Abbott	HCC	Reported June 10
41. Top fence rails broken	Back of layby opp. Police Station	Mr Abbott	HCC	Reported June 10
42. Check rail broken	Between grid and A35, Beaulieu Rd corner	Mr Abbott	HCC	Reported June 10
43. Drain sunk/manhole dropped	Corner Romsey Rd/Forest Gardens	Mr Abbott	HCC	Reported June 10
44. Pavement surface gone	Adj manhole cover outside 40 Romsey Rd	Mr Abbott	HCC	Reported June 10
45. 3no cats eye inserts missing	Adj Forest Point Hotel (may not be necessary inside 30 mph limit)	Mr Abbott	HCC	Reported June 10
46. Small pothole	Outside Forest Point/Racecourse View	Mr Abbott	HCC	Reported June 10
47. Drop from edge of road to area used for parking	Almost all along Racecourse View	Mr Abbott	HCC	Reported June 10
48. Small pothole at edge of road	Zantilly, Clarence Road	Mr Abbott	HCC	Reported June 10
49. Pothole on old Trench	Adj. 4 Clarence Road	Mr Abbott	HCC	Reported June 10
50. Road surface breaking up	Adj Kintail, Empress Rd/Pemberton Rd	Mr Abbott	HCC	Reported June 10
51. Pothole	Outside RC Church, Empress Road	Mr Abbott	HCC	Reported June 10
52. Pothole in pavement	Gosport Lane, adj slipway into the Meadows	Mr Bisson	HCC	Reported June 10
53. Overgrown hedge	Gosport Lane	Mr Bisson	HCC	Reported June 10
53. Overgrown hedge impeding pavement	Near Whitecroft, Goose Green	Mr Bisson	HCC	Reported June 10
54. Overgrown hedge	Ganders, Goose Green	Mr Bisson	HCC	Reported June 10
55. Hedge overgrowing pavement	11 The Meadows	Mr Bisson	HCC	Reported June 10