

Fault Log – October 2010

| ITEM REQUIRING ATTENTION | LOCATION | REPORTED BY | TO WHOM REPORTED | STATUS |
|--|---|-------------|------------------------------|---|
| 1. 1 slab badly broken and rising up | Mailmans Arms/Stag Hotel area | Mr Abbott | HCC (Highways) | Outstanding (Apr 10) |
| 2. Road surface/potholes | Before & adjacent to Crown Hotel | Mr Abbott | HCC (Highways) | Order with contractor (Dec 09) |
| 3. Kerbs displaced in layby | Middle of Park Close, Clayhill | Mr Abbott | HCC (Highways) | Order with contractor (Dec 09) |
| 4. Kerbs displaced in layby | Adj to post box near Crown Stirrup, Clayhill | Mr Abbott | HCC (Highways) | Order with contractor (Dec 09) |
| 5. Loose stones between highway & running strip. Some loose stones now breaking due to continual hammering | Throughout High Street | Mr Abbott | HCC (Highways) | Ongoing – long term solution might be to replace with tarmac (Dec 09) |
| 6. 20+ kerbs lose or displaced | Layby adj phone at Foxlease | Mr Abbott | HCC | Order with contractor (Dec 09) |
| 7. Red blocks loose/protruding | Between Royals and Workmens Club | Mr Abbott | HCC informed | Ongoing (Dec 09) |
| 8. Slab broken | Path from museum to coach park near path alongside museum | Mr Abbott | NFDC | Another loose slab has been done (Dec 09) |
| 9. Kerb misplaced | North side of entrance to Beechen Lane | Mr Abbott | HCC | Ongoing (Dec 09) |
| 10. Plastic post broken | Opposite Waterloo Arms | Mr Abbott | HCC | Part superseded by footpath work, 1 missing, 1 broken (Apr 10) |
| 11. Kerbs misplaced | Queens Cottage corner opposite Queens House | Mr Abbott | HCC | Ongoing (Dec 09) |
| 12. Look Left not repainted on pavement | Entrance to car park, Gosport Lane | Mr Abbott | HCC (Electrical Contractors) | Ongoing (Dec 09) |
| 13. Kerb protruding – tripping hazard | Entrance Car Park, Gosport Ln, NS | Mr Abbott | HCC | Ongoing (Dec 09) |
| 14. Safety post | Corner Gosport Lane | Mr Abbott | HCC | To be replaced (Dec 09) |
| 15. Bad potholes | Bank to Gritnam | Mr Abbott | FC | Assessed Dec 09 |
| 20. Bottom board on westbound road sign moved | Opposite Natural England | Mr Abbott | HCC | Reported Dec 09 |
| 22. Hydrant cover banging badly | Romsey Rd corner outside Antiques | Mr Abbott | HCC (Highways) | Reported Dec 09 |
| 25. Broken paving slabs | Outside Infant School | Mr Rollé | HCC (Highways) | Reported Mar 10 |
| 27. Raised manhole cover | Shrubbs Hill Road, after entrance to Shrubbs Hill Gardens | Mr Rollé | HCC (Highways) | Reported April 10 |
| 28. Cracked slabs | Outside Lyndhurst Infant School | Mr Rollé | HCC (Highways) | Reported April 10 |
| 29. Deep potholes in road | LHS corner of Garden Close | Mr Rollé | HCC (Highways) | Reported April 10 |
| 30. Bottom rail adrift on squeeze gate | Adj Lyndhurst Park Hotel | Mr Abbott | Forestry Commission | Reported April 10 |
| 31. Potholes in pavement | Outside 32 Queens Road | Mr Cornell | HCC | Reported May 10 |
| 32. General road pavement surface | Queens Road | Mr Cornell | HCC | Reported May 10 |
| 33. Overgrown hedging | Outside 20 Queens Road | Mr Cornell | HCC | Reported May 10 |
| 34. Potholes in pavement | Outside Ormonde House Hotel | Mr Cornell | HCC | Reported May 10 |
| 35. Overgrown hedging | Outside 9 Queens Road | Mr Cornell | HCC | Reported May 10 |

| ITEM REQUIRING ATTENTION | LOCATION | REPORTED BY | TO WHOM REPORTED | STATUS |
|--|---|-------------|------------------|-----------------------|
| 36. Raised BT cover/sunken surround | Opposite 3 Queens Road | Mr Cornell | HCC | Reported May 10 |
| 37. Potholes in pavement | Outside 7 Queens Road | Mr Cornell | HCC | Reported May 10 |
| 38. Raised manhole cover | Outside Meridien Garage | Mr Herbert | HCC | Reported June 10 |
| 39. Road sign partly displaced | Adj Queens Cottage | Mr Abbott | HCC | Reported June 10 |
| 40. Road sign partly displaced | Adj Church steps | Mr Abbott | HCC | Reported June 10 |
| 41. Top fence rails broken | Back of layby opp. Police Station | Mr Abbott | HCC | Reported June 10 |
| 42. Check rail broken | Between grid and A35, Beaulieu Rd corner | Mr Abbott | HCC | Reported June 10 |
| 43. Drain sunk/manhole dropped | Corner Romsey Rd/Forest Gardens | Mr Abbott | HCC | Reported June 10 |
| 44. Pavement surface gone | Adj manhole cover outside 40 Romsey Rd | Mr Abbott | HCC | Reported June 10 |
| 45. 3no cats eye inserts missing | Adj Forest Point Hotel (may not be necessary inside 30 mph limit) | Mr Abbott | HCC | Reported June 10 |
| 46. Small pothole | Outside Forest Point/Racecourse View | Mr Abbott | HCC | Reported June 10 |
| 47. Drop from edge of road to area used for parking | Almost all along Racecourse View | Mr Abbott | HCC | Reported June 10 |
| 50. Road surface breaking up | Adj Kintail, Empress Rd/Pemberton Rd | Mr Abbott | HCC | Reported June 10 |
| 52. Pothole in pavement | Gospport Lane, adj s/way into the Meadows | Mr Bisson | HCC | Reported June 10 |
| 53. Overgrown hedge | Gospport Lane | Mr Bisson | HCC | Reported June 10 |
| 53. Overgrown hedge impeding pavement | Near Whitecroft, Goose Green | Mr Bisson | HCC | Reported June 10 |
| 54. Overgrown hedge | Ganders, Goose Green | Mr Bisson | HCC | Reported June 10 |
| 55. Hedge overgrowing pavement | 11 The Meadows | Mr Bisson | HCC | Reported June 10 |
| 56. Large pothole | Westwood Road junction with Broughton Road | Resident | HCC | Reported August 10 |
| 57. Very uneven pavement surface | Outside Sofika, High Street | Mr Abbott | HCC | Reported August 10 |
| 58. Pothole in road | Corner by Queens House | Mr Abbott | HCC | Reported August 10 |
| 59. Several kerbs broken | Adjacent to Queens House | Mr Abbott | HCC | Reported August 10 |
| 61. Nameboard displaced and posts bent | Northerwood Avenue | Mr Abbott | NFDC | Reported August 10 |
| 62. Litter bin badly displaced following initial bad fitting | By post box at Emery Down Church | Mr Abbott | NFDC | Reported August 10 |
| 63. Street light post leaning towards road approx 4 ft down | No 6 near Church in High Street | Mr Abbott | HCC | Reported September 10 |
| 64. Street name sign missing | Great Mead at Shrubbs Hill end | Mr Abbott | NFDC | Reported October 10 |
| 65. Faulty drains | Outside Amberwood, Knightwood Close | Mr Boyes | HCC | Reported October 10 |