

LYNDHURST PARISH COUNCIL

Fault Log – May 2009

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
1. 6 slabs broken on pavement and piece missing from one slab	Mailmans Arms/Stag Hotel area	Mr Abbott	HCC (Highways)	* Order with contractor
2. Road surface/potholes	Before & adjacent to Crown Hotel	Mr Abbott	HCC (Highways)	* Order with contractor
3. Pothole	Garden Close entrance, lhs	Mr Abbott	HCC (Highways)	RM Still not done and deteriorating
5. Kerbs displaced in layby	Middle of Park Close, Clayhill	Mr Abbott	HCC (Highways)	* Order with contractor
6. Kerbs displaced in layby	Adj to post box near Crown Stirrup, Clayhill	Mr Abbott	HCC (Highways)	* Order with contractor
7. Loose gas cover	Stratford & Stratford	Mrs Wyeth	HCC/British Gas	Transco informed
9. Pavement holed	Outside 5 Beechen Lane	Mr Abbott/Mr Bockle	HCC (Highways)	* Footway submitted for resurfacing
10. Piece loose on BT cover	Near post box at Fox and Hounds	Mr Abbott	HCC informed	BT informed
11. Drains blocked	In front of Visitor Centre	Mr Abbott	NFDC	Ongoing
14. Loose stones between highway and running strip. Some loose stones now breaking due to continual hammering	Throughout High Street	Mr Abbott	HCC (Highways)	Ongoing – long term solution might be to replace with tarmac
15. 20+ kerbs lose or displaced	Layby adj phone at Foxlease	Mr Abbott	HCC	* Order with contractor
16. Bollard uprooted/path broken up	Church Lane (on right opposite Bathroom Store back entrance)	Mrs Butcher	HCC	Order yet to be raised
17. Three lamp posts out	Between Swan Green and Emery Down at Lyndhurst Hill	Mrs Trend	HCC informed	Street lighting
18. Road puddle – surface lifting	Near island – G/Green/Shrubbs Hill		HCC informed	Order yet to be raised
19. Grating on pavement sticking up	Outside bead shop leading to Crown Hotel steps	Mrs Wyeth	HCC informed	Owner to be contacted
20. Hedge overgrown	Goose Green (White Front to Ganders			Further letter to owner, hedge cut but not enough
21. Pavement in bad condition and considered hazard	Rufus Court to slip road, Gosport Lane	Mrs Wyeth	HCC informed	*S Ongoing. Marked to be done 28.04.09
23. Broken slab at angle/hazard	Outside Meridien Garage	Mr Abbott	HCC informed	Ongoing
26. Street Light	Opp. Entrance to Rufus Court	Mr Gailor	HCC informed	Street lighting
27. Red blocks lose/protruding	Between Royals and Workingmen's Club	Member of public/Mr Abbott	HCC informed	*S Ongoing
29. Visibility of school warning signs	A35/Shrubbs Hill Road	Mrs Wyeth	HCC informed	Ongoing
30. Faulty paving slab	Outside Renaissance	Miss Wickens	HCC informed	HCC will rectify temporarily
31. Direction sign now dangerous	By Church/Queens Cottage and also at Shrubbs Hill	Mr Bisson	HCC informed	Is this the sign near Stydd House? Sign at the Church has been done
33. Hole where post is missing	By footpath opposite Waterloo PH	Mrs Bisson	HCC informed	Order not yet raised

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
35. Hedge overhanging footpath	Holly Lodge, Queens Parade	Local resident	Owners informed	Remedial action to be taken
36. Hedge overhanging footpath	Adjacent Fenwick Hospital	Local resident	PCT informed	Ongoing
38. Several bollards missing	Road at far side of Goose Green	Mrs Butcher	HCC informed	*S Order with contractor
39. Various undulations in road	Shrubbs Hill Road/Clay Hill/Gosport Lane	Resident/Mr Wilding/Mr Bockle	Rob Millar at HCC informed	* Order with contractor to carry out some patching, resurfacing required Gosport Lane
40. Overgrown hedge	Left hand corner entering Knightwood Avenue	Mr Boyes	HCC informed	Letter to be sent to owner
41. Slab broken	Path from museum to coach park near path alongside museum	Mr Abbott	NFDC	Another loose slab has been done
43. Surround of stopcock cover breaking up	Outside Passage to India, Romsey Road	Mr Abbott	Southern Water	Ongoing
44. Kerb misplaced	North side of entrance to Beechen Lane	Mr Abbott	HCC	* Ongoing
46. Bad edge on reinstated trench	Road to Gales Green (behind)	Mr Abbott	HCC	RM Ongoing
47. Plastic post broken	Opposite Waterloo Arms	Mr Abbott	HCC	Ongoing
48. Bad drop edge of road	Racecourse View opposite Forest Point Hotel	Mr Abbott	HCC	RM Ongoing
49. Three fence rails broken	Opposite 9 Racecourse View	Mr Abbott	HCC	* Ongoing
50. Kerbs misplaced	Queens Cottage corner opposite Queens House	Mr Abbott	HCC	* Ongoing
51. Gully needs clearing/very slow to clear water	LHS Shrubbs Hill Road by wall of Corylus Cottage	Mr Abbott	HCC	RM Still flooded 28.04.09
53. Look Left not repainted on pavement	Entrance to car park, Gosport Lane	Mr Abbott	HCC (Electrical Contractors)	* SOngoing
55. Path in poor condition	Chapel Lane	Mr Charlesworth	HCC	Ongoing
56. Kerb stone out of place	RHS Chapel Lane corner with A35	Mr Charlesworth/Mr Rollé	HCC	* Ongoing
57. Broken slabs	Adjacent to school, near crossing	Mr Rollé	HCC	RM Query specification of slabs or sign indicating not suitable for heavy vehicles
58. Layby sunk and flooding + possible drain blockage	Beechings Over, Goose Green	Mrs Butcher	HCC	Ongoing
59. Overgrown trees etc	Mark Abbott, Goose Green	Mrs Butcher	HCC	Ongoing
60. Water leaking from manhole	Gosport Lane – between Spellowdale and Oakwood	Mr Bisson	HCC	RM Ongoing
61. Overgrown Leylandii	Gosport Lane – RHS past pedestrian access to The Meadows	Mr Bisson	HCC	RM Ongoing

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
62. Sunken kerb protruding – tripping hazard	Entrance to Car Park, Gosport Lane, North side	Mr Abbott	HCC	* S Ongoing
64. Five bar gate broken	Opposite 9 Racecourse View	Mr Abbott	HCC	Ongoing
67. Drain cover noisy	Just after Appletree Court entrance, Gosport Lane	Mr Abbott	HCC	Ongoing
68. Loose paving slab	Outside Heppenstalls, High Street	Miss Wickens	HCC	Ongoing
69. Loose paving slab	Outside Pharmacy	Mrs Bisson	HCC	Ongoing
70. Broken “The Meadows” signage	Gosport Lane end of footpath in The Meadows	Mr Abbott	NFDC	Ongoing
71. Fence board missing (x2)	Top of Bench Hill	Mr Abbott	FC	Ongoing
73. Indistinguishable kerb	Prezzo/Holiday Shop	Mrs Wyeth	HCC	Ongoing
74. Safety post	Corner Gosport Lane	Mr Abbott	HCC	RM To be replaced
75. Bad surface of path	Corner Shrubbs Hill/Goose Green	Mr Abbott	HCC	RM
76. Verges to reinstate	Northerwood Ave/Garden Close	Mr Abbott	Gas contractors	RM
77. Bad potholes	Bank to Gritnam	Mr Abbott	FC	
78. Hole and pump in pavement	Outside Sofika 6 High Street	Mr Abbott	HCC	RM
79. Bad ponding (half way over road)	By Manor boundary stone, opp Myrtle Tree Cottage	Mr Abbott	HCC	RM

* Major items to Rob Millar on 23.04.09

*S Considered safety hazard

RM Rob Millar saw on rounds in addition to fault items marked *