

Fault Log – April 2011

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
1. 1 slab badly broken and rising up	Mailmans Arms/Stag Hotel area	Mr Abbott	HCC (Highways)	Patched with tar – new stone needed
2. Road surface/potholes	Partly completed/some rough area	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
3. Kerbs displaced in layby	Middle of Park Close, Clayhill	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
4. Kerbs displaced in layby	Adj to post box near Crown Stirrup, Clayhill	Mr Abbott	HCC (Highways)	Order with contractor (Dec 09)
5. Loose stones between highway & running strip. Some loose stones now breaking due to continual hammering	Throughout High Street	Mr Abbott	HCC (Highways)	Ongoing – long term solution might be to replace with tarmac (Dec 09)
6. 20+ kerbs lose or displaced	Layby adj phone at Foxlease	Mr Abbott	HCC	Order with contractor (Dec 09)
7. Red blocks loose/protruding	Between Royals and Workmens Club	Mr Abbott	HCC informed	Ongoing (Dec 09)
9. Kerb misplaced	North side of entrance to Beechen Lane	Mr Abbott	HCC	Ongoing (Dec 09)
10. Plastic post broken	Opposite Waterloo Arms	Mr Abbott	HCC	Part superseded by footpath work, 1 missing, 1 broken (Apr 10)
11. Kerbs misplaced	Queens Cottage corner opposite Queens House	Mr Abbott	HCC	Ongoing (Dec 09)
12. Large road sign flattened by vehicle	Goose Green – opposite Corner Cottage	Mr Abbott	HCC	Ongoing (Dec 10)
13. Kerb protruding – tripping hazard	Entrance Car Park, Gosport Ln, NS	Mr Abbott	HCC	Ongoing (Dec 09)
14. Safety post	Corner Gosport Lane	Mr Abbott	HCC	To be replaced (Dec 09)
20. Bottom board on westbound road sign moved	Opposite Natural England	Mr Abbott	HCC	Reported Dec 09
22. Hydrant cover banging badly	Romsey Rd corner outside Antiques	Mr Abbott	HCC (Highways)	Reported Dec 09
25. Broken paving slabs	Outside Infant School	Mr Rollé	HCC (Highways)	Reported Mar 10
27. Raised manhole cover	Shrubbs Hill Road, after entrance to Shrubbs Hill Gardens	Mr Rollé	HCC (Highways)	Reported April 10
28. Cracked slabs	Outside Lyndhurst Infant School	Mr Rollé	HCC (Highways)	Reported April 10
31. Potholes in pavement	Outside 32 Queens Road	Mr Cornell	HCC	Reported May 10
32. General road pavement surface	Queens Road	Mr Cornell	HCC	Reported May 10
33. Overgrown hedging	Outside 20 Queens Road	Mr Cornell	HCC	Reported May 10
34. Potholes in pavement	Outside Ormonde House Hotel	Mr Cornell	HCC	Reported May 10
35. Overgrown hedging	Outside 9 Queens Road	Mr Cornell	HCC	Reported May 10
36. Raised BT cover/sunken surround	Opposite 3 Queens Road	Mr Cornell	HCC	Reported May 10
37. Potholes in pavement	Outside 7 Queens Road	Mr Cornell	HCC	Reported May 10
38. Raised manhole cover	Outside Meridien Garage	Mr Herbert	HCC	Reported June 10
39. Road sign partly displaced	Adj Queens Cottage	Mr Abbott	HCC	Reported June 10

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
40. Road sign partly displaced	Adj Church steps	Mr Abbott	HCC	Reported June 10
42. Rails broken	Between grid and A35, Beaulieu Rd corner	Mr Abbott	HCC	Reported June 10
43. Drain sunk/manhole dropped	Corner Romsey Rd/Forest Gardens	Mr Abbott	HCC	Reported June 10
44. Pavement surface gone	Adj manhole cover outside 40 Romsey Rd	Mr Abbott	HCC	Reported June 10
45. 3no cats eye inserts missing	Adj Forest Point Hotel (may not be necessary inside 30 mph limit)	Mr Abbott	HCC	Reported June 10
46. Small pothole	Outside Forest Point/Racecourse View	Mr Abbott	HCC	Reported June 10
47. Drop from edge of road to area used for parking	Almost all along Racecourse View	Mr Abbott	HCC	Reported June 10
50. Road surface breaking up	Adj Kintail, Empress Rd/Pemberton Rd	Mr Abbott	HCC	Reported June 10
52. Pothole in pavement	Gosport Lane, adj s/way into the Meadows	Mr Bisson	HCC	Reported June 10
53. Overgrown hedge	Gosport Lane	Mr Bisson	HCC	Reported June 10
53. Overgrown hedge impeding pavement	Near Whitecroft, Goose Green	Mr Bisson	HCC	Reported June 10
54. Overgrown hedge	Ganders, Goose Green	Mr Bisson	HCC	Reported June 10
55. Hedge overgrowing pavement	11 The Meadows	Mr Bisson	HCC	Reported June 10
56. Large pothole	Westwood Road junction with Broughton Road	Resident	HCC	Reported August 10
57. Very uneven pavement surface	Outside Sofika, High Street	Mr Abbott	HCC	Reported August 10
58. Pothole in road	Corner by Queens House	Mr Abbott	HCC	Reported August 10
59. Several kerbs broken	Adjacent to Queens House	Mr Abbott	HCC	Reported August 10
62. Litter bin badly displaced following initial bad fitting	By post box at Emery Down Church	Mr Abbott	NFDC	Reported August 10
63. Street light post leaning towards road approx 4 ft down	No 6 near Church in High Street	Mr Abbott	HCC	Reported September 10
64. Street name sign missing	Great Mead at Shrubbs Hill end	Mr Abbott	NFDC	Reported October 10
66. 3 pales missing/1 broken fence	Top of Bench Hill	Mr Abbott	FC	Reported November 10/February 11
68. Drain cover rusted and loose	Corner of 12 Hillary Close	Mr Abbott	NFDC	Reported November 10
69. Gate closing post loose	Gate from Westwood Road to Forest near Homelands	Mr Abbott	FC	Reported November 10
70. Rails of car park distorted towards path	Wellands Road car park	Mr Abbott	NFDC	Reported November 10
71. Road sign dented	Gosport Lane opposite Vernals Farm field gate	Mr Abbott	HCC	Reported November 10
72. Manhole cover low	Outside cottage at corner of Goose Green	Mr Abbott	HCC	Reported December 10
73. Small cover low	Outside The Orchards, Shrubbs Hill	Mr Abbott	HCC	Reported December 10

ITEM REQUIRING ATTENTION	LOCATION	REPORTED BY	TO WHOM REPORTED	STATUS
74. Two covers low and noisy (large and small)	Outside Spring Cottage, Shrubbs Hill	Mr Abbott	HCC	Reported December 10
75. Water slow getting away at drain in LHS kerb causing splashing to anyone on pavement	Just past bend going up hill to Queens Cottage	Mr Abbott	HCC	Reported December 10
76. Road surface breaking up	High Street to Gosport Lane	Mr Abbott	HCC	Reported December 2010
77. Road surface breaking up around manhole	Gosport Lane entrance to car park	Mr Abbott	HCC	Reported December 2010
78. Faulty drains	Outside Amberwood, Knightwood Close	Mr Boyes	HCC	Reported October 10
79. Surround to water stop cock cover broken up	Outside "Passage to India" restaurant, Romsey Road	Mr Abbott	HCC	Reported February 11
80. Highway breaking up	Outside 74 High Street	Mr Abbott	HCC	Reported February 11
81. Pothole on edge of road	Opposite entrance to Oakacre (B3056)	Mr Abbott	HCC	Reported February 11
82. Pothole at side of manhole	Outside Beehive Cottage, bottom of Emery Down Hill	Mr Abbott	HCC	Reported February 11
83. Water running out of blocked drain over pavement and road	Entrance to Northerwood Avenue	Mr Abbott	HCC	Reported February 11
84. Pothole in road	Between grid and Northerwood Avenue turning on left hand side approaching from Emery Down hill	Mr Abbott	HCC	Reported February 11
85. Several potholes	Lane to Pondhead Farm, all before bridge over stream	Mr Abbott	HCC	Reported February 11
86. Pothole on edge of road	Beaulieu Road, adjacent to Bolton's Bench	Mr Abbott	HCC	Reported February 11
88. Light failure in solar powered bollard	Romsey Road, near Police Station	Mr Abbott	HCC	Reported February 11
89. Road verge crumbling	Verge outside Halemede, Emery Down	Mrs Trend	HCC	Reported March 2011
90. Pothole in road	Outside Halemede, Emery Down	Mrs Trend	HCC	Reported March 2011
91. Crumbling verge	Myrtle Cottage gateway, Emery Down	Mrs Trend	HCC	Reported March 2011
92. Crumbling verges	Virginia Cottage/Sunnydale, Emery Down	Mrs Trend	HCC	Reported March 2011
93. Pothole	Opposite Virginia Cottage, Emery Down	Mrs Trend	HCC	Reported March 2011
94. Road repairs eroding	Near Rose Cottage, Emery Down	Mrs Trend	HCC	Reported March 2011
95. Two potholes	Opposite Walden, Emery Down	Mrs Trend	HCC	Reported March 2011
96. Road repair sunk and eroding	Walden and Oakover, Emery Down	Mrs Trend	HCC	Reported March 2011
97. Pothole	Opposite Oakover, Emery Down	Mrs Trend	HCC	Reported March 2011
98. Verge eroding	Outside Oakover	Mrs Trend	HCC	Reported March 2011
99. Hole in repair work	Springwood, Emery Down	Mrs Trend	HCC	Reported March 2011

